U.S. Officials Only CONFIDENTIAL,

CENTRAL INTELLIGENCE AGENCY

25X1A

4

INFORMATION REPORT

COUNTRY Angola
SUBJECT Porto Amboim, Port Information

PLACE ACQUIRED (BY SOURCE)

DATE ACQUIRED (BY SOURCE)

DATE (OF INFO.)

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DIFENSE
OF THE UNITED STATES, BITMIN THE MERANING OF FITLE 18 SECTIONS 763
AND 784. OF THE U.S. CODE. AS AMENOEU. ITS TRANSMISSION OF REVEL
LATION OF ITS CONTENTS TO GA RECEIPT BY AN UNAUTHORIZED PERSON IS
AGAINSTITED BY LAB. THE REPORDUCTION OF THIS REPORT IS PARMISSITED.

25X1A

THIS IS UNEVALUATED INFORMATION

REPORT NO.		
CO NO.		
00/C NO.		
ORR NO.		
DAS NO.		
OCI NO.		

NO. OF PAGES 2

DATE DISTR.

NO. OF ENCLS.

SUPP. TO REPORT NO.

SOURCE Officer of a US merchant ship.

The Office of Naval Intelligence furnished the following information to CIA for IAC dissemination in accordance with paragraph 3c of NSCID #7. This information was obtained by D10-3ND and was forwarded as ONI report 17-54.7

- 1. General: Porto Amboim (Lat 10° 43' 51" S, Long 13° 44' 59" E) is a slight indentation in the coast of Angola on the West African coast. It is an open export, the main traffic in the port, is worked by lighters. The town of Amboim is small with about 30 houses and a few stores.
- Hydrography: The water off Porto Amboim is deep. It drops off suddenly reaching a depth of 10 fathoms within 500 feet of the beach. The port can be approached from any direction from northwest through southwest. The outstanding landmark is a high bluff resembling a sugar-loaf on which a light is located. A recommended approach is to place the high bluff on a true bearing of 0900 and follow that heading. A small finger pier marked by red and green lights is situated near the base of the bluff.
- 3. Lighterage: All cargo is worked by lighters, eight with approximate capacities of 60 tons the port, the lighters must either be shifted by hand line or moved by ship's own craft. The source prefers the latter alternative and uses a motor lifebont. When using the hand-line method, a ship should moor close to a buoy located means of this lighters can be shuttled between ship and pier using lines handled by native labor.
- 4. Pier: Built about May 1953, the finger pier is 75 feet long by about 25 feet wide. It is constructed of steel pilings with wooden decking and supports a small crane and a narrow gauge railway. The depth of water at its seaward end is about 30 feet, and although it is believed possible to bring a ship to the pier, it is dangerous and impractical because lighterage would still be required to work the ship's cargo. The pier is used to service lighters.
- 5. Crane: The crane is an old steam-powered, railway lift of the derrick type and is capable of handling up to five tons. It is moved by native labor.

ONI DECLASSIFICATION/RELEASE INSTRUCTIONS ON FILE

DISTRIBUTION IN STATE

U.S. Officials Only

SEE LAST PAGE FOR SUBJECT & AREA CULLIARMY NAZY AIR FOI

This report is for the use within the USA of the Intelligence components of the Departments or originating office through the Assistant 003/10/01the CPACR PP80-00809A0005500450.179.2

Approved For Release 2003/10/01 : CIA-RDP80-00809A000500450179-2

CONFIDENTIAL/US OFFICIALS ONLY

-2-

25X1A

- 6. Railway: Two narrow gauge tracks running the length of the pier join into a single track leading the half-mile to the coffee warehouses. The rolling stock consists of several flat cars 10' by 4' and one small diesel engine.
- 7. Warehouses: Coffee for export is stored in three warehouses. These are of cement construction with clay tile roofing and are one story high, about 200 feet long by 75 feet wide.
- 8. Labor: Natives provide unskilled labor, while such skilled tasks as operating the crane and the railway are performed by Portugese labor. Ships provide their own stevedore manpower as a rule.
- 9. Communications: Porto Amboim is in telephone contact with Luanda and has telegraph lines to both Luanda and Lobito.
- Clearance Facilities: The primary avenue of communication with the outside world is the sea. No railroad is reported, and the only road is a poor road to Luanda which is not recommended for vehicles much larger than jeeps.

-end-

CONFIDENTIAL/US OFFICIALS ONLY

LIBRARY SUBJECT & AREA CODES

756.548	1
756.545	- 1
756.543	1.
756.549	1.
756.544	1.